





**500 MAIN GEARBOX 1)**

| Pos. | Part No.             | Description       | Dimension     | Quantity | Conditions |
|------|----------------------|-------------------|---------------|----------|------------|
| 1    | <b>00 0236 172 0</b> | HEXAGONAL NUT     | M12           | 2        |            |
| 2    | <b>00 0239 389 0</b> | CONTACT WASHER    | A12           | 2        |            |
| 3    | <b>00 0810 117 0</b> | BUSHING           | D30X20        | 2        |            |
| 4    | <b>00 0843 463 0</b> | GUARD CUP         | D206X1.5      | 1        |            |
| 5    | <b>00 0239 387 0</b> | CONTACT WASHER    | A8-8,2X18X1,4 | 3        |            |
| 6    | <b>00 0237 439 0</b> | HEXAGON HEAD BOLT | M8X16         | 3        |            |
| 7    | <b>00 0235 089 0</b> | SPLIT PIN         | 4 X 22        | 1        | 2)         |
| 8    | <b>00 0608 099 0</b> | ROUND STEEL CHAIN | G 3X16-17GL   | 1        | 2)         |
| 9    | <b>00 0233 918 0</b> | HEXAGON HEAD BOLT | M 5X16        | 1        | 2)         |
| 9    | <b>00 0236 910 2</b> | FLAT WASHER       | 5 -5,3X10X1   | 1        | 2)         |
| 9    | <b>00 0237 216 0</b> | HEXAGONAL NUT     | M05           | 1        | 2)         |
| 10   | <b>00 0868 298 0</b> | PROTECTIVE TUBE   | D 110 X 488LG | 1        | 3)         |
| 10   | <b>00 0821 067 2</b> | PROTECTIVE TUBE   | D 110 X 493LG | 1        | 4)         |
| 11   | <b>00 0237 922 1</b> | BLIND RIVET       | A 4X12        | 1        |            |
| 12   | <b>00 0822 998 1</b> | LOCK              |               | 1        |            |
| 13   | <b>00 0822 996 0</b> | PROTECT.TUBE CPL. |               | 1        |            |
| 14   | <b>00 0243 065 0</b> | CIRCLIP           | 130X4         | 1        |            |
| 15   | <b>00 0215 768 0</b> | GRVD.BALL BEARING | 6312-2RS*     | 1        |            |
| 16   | <b>00 0843 465 0</b> | BEARING           |               | 1        |            |
| 17   | <b>00 0836 261 1</b> | PIN               | D25X48        | 1        |            |
| 18   | <b>00 0234 238 0</b> | WASHER            | 26X42X1       | 1        |            |
| 19   | <b>00 0237 033 0</b> | SPLIT PIN         | 6,3X 40       | 1        |            |

|           |                    |             |                         |
|-----------|--------------------|-------------|-------------------------|
| <b>1)</b> | <b>Equipment</b>   | PR_P08_0020 | Input gearbox 1,000 rpm |
| <b>2)</b> | <b>machine no.</b> |             | + up to 77000375        |
| <b>3)</b> | <b>machine no.</b> |             | + from 77000606         |
| <b>4)</b> | <b>machine no.</b> |             | + up to 77000605        |

E0522 0230A500A 2



**500 MAIN GEARBOX 1)**

| Pos. | Part No.             | Description       | Dimension            | Quantity | Conditions |
|------|----------------------|-------------------|----------------------|----------|------------|
| 1    | <b>00 0844 729 0</b> | GEARBOX           | I=5,38               | 1        |            |
| 2    | <b>00 0827 578 0</b> | BEVEL GEAR SET    |                      | 1        |            |
| 3    | <b>00 0243 685 0</b> | TA.ROLLER BEARING | 30310 - 50X110X29,25 | 1        |            |
| 4    | <b>00 0211 966 0</b> | SHIM              | 100X110X1            | 1        |            |
| 4    | <b>00 0211 964 0</b> | SHIM              | 100X110X0,3          | 1        |            |
| 4    | <b>00 0211 963 0</b> | SHIM              | 100X110X0,1          | 1        |            |
| 5    | <b>00 0237 442 0</b> | HEXAGON HEAD BOLT | M8X25                | 12       |            |
| 6    | <b>00 0827 580 0</b> | COVER             |                      | 1        |            |
| 7    | <b>00 0827 577 1</b> | HOUSING           |                      | 1        |            |
| 8    | <b>00 0238 183 0</b> | SEALING RING      | A16 X20              | 4        |            |
| 9    | <b>00 0827 581 0</b> | BREATHER VALVE    | 1021-04-401-00       | 1        |            |
| 10   | <b>00 0234 829 0</b> | TA.ROLLER BEARING | 30209 J2/Q           | 2        |            |
| 11   | <b>00 0213 961 0</b> | SHAFT SEAL        | AS 30X 55X10         | 1        |            |
| 12   | <b>00 0851 341 0</b> | SHAFT             |                      | 1        |            |
| 13   | <b>00 0211 034 0</b> | ROTARY SHAFT SEAL | AS 60X 85X 8         | 1        |            |
| 14   | <b>00 0243 661 0</b> | TA.ROLLER BEARING | 30212A               | 1        |            |
| 15   | <b>00 0823 993 0</b> | SLOTTED NUT       | M55X1,5              | 1        |            |
| 16   | <b>00 0244 014 1</b> | STUD BOLT         | M12X 45              | 2        |            |
| 17   | <b>00 0244 351 0</b> | SCREW PLUG        | M16X1,5              | 3        |            |
| 18   | <b>00 0823 994 0</b> | SLOTTED NUT       | M45X1,5              | 1        |            |
| 19   | <b>00 0213 766 0</b> | SHAFT SEAL        | AS 40X 90X12         | 1        |            |

**1) Equipment**

PR\_P08\_0020

Input gearbox 1,000 rpm



**500 MAIN GEARBOX 1)**

| Pos. | Part No.             | Description       | Dimension     | Quantity | Conditions |
|------|----------------------|-------------------|---------------|----------|------------|
| 1    | <b>00 0236 172 0</b> | HEXAGONAL NUT     | M12           | 1        |            |
| 2    | <b>00 0239 389 0</b> | CONTACT WASHER    | A12           | 1        |            |
| 3    | <b>00 0810 117 0</b> | BUSHING           | D30X20        | 1        |            |
| 4    | <b>00 0843 463 0</b> | GUARD CUP         | D206X1.5      | 1        |            |
| 5    | <b>00 0239 387 0</b> | CONTACT WASHER    | A8-8,2X18X1,4 | 3        |            |
| 6    | <b>00 0237 439 0</b> | HEXAGON HEAD BOLT | M8X16         | 3        |            |
| 7    | <b>00 0235 089 0</b> | SPLIT PIN         | 4 X 22        | 1        | 2)         |
| 8    | <b>00 0608 099 0</b> | ROUND STEEL CHAIN | G 3X16-17GL   | 1        | 2)         |
| 9    | <b>00 0233 918 0</b> | HEXAGON HEAD BOLT | M 5X16        | 1        | 2)         |
| 9    | <b>00 0236 910 2</b> | FLAT WASHER       | 5 -5,3X10X1   | 1        | 2)         |
| 9    | <b>00 0237 216 0</b> | HEXAGONAL NUT     | M05           | 1        | 2)         |
| 10   | <b>00 0868 298 0</b> | PROTECTIVE TUBE   | D 110 X 488LG | 1        | 3)         |
| 10   | <b>00 0821 067 2</b> | PROTECTIVE TUBE   | D 110 X 493LG | 1        | 4)         |
| 11   | <b>00 0237 922 1</b> | BLIND RIVET       | A 4X12        | 4        |            |
| 12   | <b>00 0822 998 1</b> | LOCK              |               | 2        |            |
| 13   | <b>00 0822 996 0</b> | PROTECT.TUBE CPL. |               | 1        |            |
| 14   | <b>00 0243 065 0</b> | CIRCLIP           | 130X4         | 1        |            |
| 15   | <b>00 0215 768 0</b> | GRVD.BALL BEARING | 6312-2RS*     | 1        |            |
| 16   | <b>00 0843 465 0</b> | BEARING           |               | 1        |            |
| 17   | <b>00 0836 261 1</b> | PIN               | D25X48        | 1        |            |
| 18   | <b>00 0234 238 0</b> | WASHER            | 26X42X1       | 1        |            |
| 19   | <b>00 0237 033 0</b> | SPLIT PIN         | 6,3X 40       | 1        |            |

**1) Equipment**

PR\_P08\_0010

Input gearbox 540 rpm

**2) machine no.**

+ up to 77000375


**3) machine no.**

+ from 77000606

**4) machine no.**

+ up to 77000605


E0522 0230A500B 2



**500 MAIN GEARBOX 1)**

| Pos. | Part No.      | Description       | Dimension                   | Quantity | Conditions |
|------|---------------|-------------------|-----------------------------|----------|------------|
| 1    | 00 0843 460 1 | GEARBOX           | I=2,89                      | 1        |            |
| 2    | 00 0851 341 0 | SHAFT             |                             | 1        |            |
| 3    | 00 0211 034 0 | ROTARY SHAFT SEAL | AS 60X 85X 8                | 1        |            |
| 4    | 00 0213 765 0 | SHIM              | 85X 95X0,5                  | 2        |            |
| 4    | 00 0213 764 0 | SHIM              | 85X 95X0,3                  | 1        |            |
| 4    | 00 0213 962 0 | SHIM              | 85X 95X0,1                  | 2        |            |
| 5    | 00 0212 210 0 | TA.ROLLER BEARING | 330 12                      | 1        |            |
| 6    | 00 0823 942 0 | BEVEL GEAR SET    | I=2,88                      | 1        |            |
| 7    | 00 0823 993 0 | SLOTTED NUT       | M55X1,5                     | 1        |            |
| 8    | 00 0244 014 1 | STUD BOLT         | M12X 45                     | 2        |            |
| 9    | 00 0844 564 0 | HOUSING           |                             | 1        |            |
| 10   | 00 0238 183 0 | SEALING RING      | A16 X20                     | 4        |            |
| 11   | 00 0940 866 0 | BREATHER VALVE    | M 16X1,5 M.<br>SPRITZROHR   | 1        |            |
| 12   | 00 0234 829 0 | TA.ROLLER BEARING | 30209 J2/Q                  | 2        |            |
| 13   | 00 0213 961 0 | SHAFT SEAL        | AS 30X 55X10                | 1        |            |
| 14   | 00 0244 351 0 | SCREW PLUG        | M16X1,5                     | 3        |            |
| 15   | 00 0243 686 0 | TA.ROLLER BEARING | 30311A - 55X120X31,5        | 1        |            |
| 16   | 00 0214 179 0 | SHIM              | 110X120X0,1 ERS.D.<br>21417 | 2        |            |
| 16   | 00 0214 180 0 | SHIM              | 110X120X0,3 ERS.D.<br>21418 | 1        |            |
| 16   | 00 0214 181 0 | SHIM              | 110X120X0,5 ERS.D.<br>21418 | 1        |            |
| 17   | 00 0237 572 0 | HEXAGON HEAD BOLT | M12X35                      | 8        |            |
| 18   | 00 0844 565 0 | BEARING HOUSING   |                             | 1        |            |
| 19   | 00 0823 994 0 | SLOTTED NUT       | M45X1,5                     | 1        |            |
| 20   | 00 0213 766 0 | SHAFT SEAL        | AS 40X 90X12                | 1        |            |
|      |               |                   |                             |          |            |
| 1)   | Equipment     |                   |                             |          |            |
|      |               | PR_P08_0010       | Input gearbox 540 rpm       |          |            |
|      |               |                   |                             |          |            |






E0522 0260A100A 1

100 DRIVE SHAFT, MAIN DRIVE 1)

| Pos. | Part No.      | Description       | Dimension                                                   | Quantity | Conditions |
|------|---------------|-------------------|-------------------------------------------------------------|----------|------------|
| 1    | 00 0836 975 0 | DRIVE SHAFT       |                                                             | 1        |            |
| 2    | 00 0836 980 0 | FORK              |                                                             | 1        |            |
| 3    | 00 0836 981 0 | CENTRE CROSS ASS. |                                                             | 2        |            |
| 4    | 00 0836 983 0 | FORK              |                                                             | 1        |            |
| 5    | 00 0836 982 0 | INNER FORK        |                                                             | 1        |            |
| 6    | 00 0234 862 0 | SPRING PIN        | 10 X100                                                     | 1        |            |
| 7    | 00 0836 984 0 | PROFILE TUBE EXT. |                                                             | 1        |            |
| 8    | 00 0244 579 0 | SPRING PIN        | 10X65                                                       | 1        |            |
| 9    | 00 0836 989 0 | PROFILE TUBE INT. |                                                             | 1        |            |
| 10   | 00 0941 903 0 | FORK              |                                                             | 1        |            |
| 11   | 00 0138 307 0 | CENTRE CROSS ASS. |                                                             | 1        |            |
| 12   | 00 0836 985 0 | SHEAR BOLT CLUTCH |                                                             | 1        |            |
| 13   | 00 0844 557 0 | RING              |                                                             | 1        |            |
| 14   | 00 0844 558 0 | RING              |                                                             | 1        |            |
| 15   | 00 0836 978 0 | GUARD HALF        |                                                             | 1        |            |
| 16   | 00 0836 979 0 | GUARD HALF        |                                                             | 1        |            |
| 17   | 00 0836 346 0 | RING              |                                                             | 1        |            |
|      |               |                   |                                                             |          |            |
| 1)   | Equipment     | PR_M04_0010       | Single wide-angle PTO drive shaft with shearbolt, 6 splines |          |            |




100 DRIVE SHAFT, MAIN DRIVE 1)

| Pos. | Part No.      | Description               | Dimension | Quantity | Conditions |
|------|---------------|---------------------------|-----------|----------|------------|
| 1    | 00 0836 985 0 | SHEAR BOLT CLUTCH         |           | 1        |            |
| 2    | 00 0235 534 1 | HEXAGON HEAD BOLT         | M10X50X29 | 1        |            |
| 3    | 00 0237 947 0 | HEX. NUT WITH CLAMP. PART | M10       | 1        |            |
| 4    | 00 0236 942 0 | GREASE NIPPLE             | A S6X1    | 1        |            |
| 5    | 00 0836 986 0 | SLIDING PIN               |           | 1        |            |


|    |           |             |                                                             |
|----|-----------|-------------|-------------------------------------------------------------|
| 1) | Equipment | PR_M04_0010 | Single wide-angle PTO drive shaft with shearbolt, 6 splines |
|----|-----------|-------------|-------------------------------------------------------------|

E0522 0260A100B 1



100 DRIVE SHAFT, MAIN DRIVE 1)

| Pos. | Part No.      | Description       | Dimension                                              | Quantity | Conditions |
|------|---------------|-------------------|--------------------------------------------------------|----------|------------|
| 1    | 00 0843 751 0 | DRIVE SHAFT ASSY. |                                                        | 1        |            |
| 2    | 00 0843 775 0 | FORK              |                                                        | 1        |            |
| 3    | 00 0843 765 0 | CENTRE CROSS ASS. |                                                        | 2        |            |
| 4    | 00 0843 767 0 | FORK              |                                                        | 1        |            |
| 5    | 00 0843 766 0 | INNER FORK        |                                                        | 1        |            |
| 6    | 00 0234 862 0 | SPRING PIN        | 10 X100                                                | 1        |            |
| 7    | 00 0843 768 0 | TUBE              |                                                        | 1        |            |
| 8    | 00 0244 579 0 | SPRING PIN        | 10X65                                                  | 1        |            |
| 9    | 00 0843 773 0 | TUBE              |                                                        | 1        |            |
| 10   | 00 0843 772 0 | FORK              |                                                        | 1        |            |
| 11   | 00 0843 771 0 | CENTRE CROSS ASS. |                                                        | 1        |            |
| 12   | 00 0843 769 0 | SHEAR BOLT CLUTCH |                                                        | 1        |            |
| 13   | 00 0844 557 0 | RING              |                                                        | 1        |            |
| 14   | 00 0844 558 0 | RING              |                                                        | 1        |            |
| 15   | 00 0843 762 0 | GUARD HALF        |                                                        | 1        |            |
| 16   | 00 0866 429 0 | GUARD             |                                                        | 1        |            |
| 17   | 00 0836 346 0 | RING              |                                                        | 1        |            |
| 1)   | Equipment     | PR_M04_0020       | Single wide-angle universal drive shaft with shearbolt |          |            |



Thank you so much for reading.  
Please click the “Buy Now!”  
button below to download the  
complete manual.



After you pay.

You can download the most  
perfect and complete manual in  
the world immediately.

Our support email:

[ebooklibonline@outlook.com](mailto:ebooklibonline@outlook.com)